

# Information International Business Partners

Zollikofen, July 2022

Dear Partner

# Updated information regarding the current delivery issues

Delivery information are now regularly updated online, also the letters are available for download under this link: www.securiton.com/newsds.

The global shortage on electronic components combined with a high market demand remains challenging. Due to more constant and higher production output, the lead-times on many products could be shortened in the past weeks.

Please allow for a lead-time – ex works – of at least 12 weeks for all products that are not explicitly mentioned in this letter.

# Situation SecuriSmoke ASD and SecuriHeat ADW

ASD 531, ASD 532, ASD 533, ASD 535

The production of all ASD models keeps running at full capacity.

SSD 532-3, SSD 535-3

The production is running at full capacity.

ASD 531	33 – 39 weeks
ASD 532	34 – 35 weeks
ASD 533	10 – 15 weeks
ASD 535-1	22 – 26 weeks
ASD 535-2	21 – 23 weeks
ASD 535-3	28 – 33 weeks
ASD 535-4	25 – 31 weeks
ASD 535-3 HD / 535-4 HD	12 – 22 weeks / 27 – 34 weeks
SSD 532-3	18 – 24 weeks
SSD 535-3	18 – 20 weeks
SIM 35	31 – 34 weeks
RIM 35 / RIM 36	21 – 27 weeks / 27 – 32 weeks

# ADW 535

Production is running at full capacity.

ADW 535-1	12 – 16 weeks
ADW 535-2	16 – 20 weeks

# Situation Fire Alarm System SecuriFire

SecuriFire Fire Alarm Control Panels:

Production has resumed at limited capacity. The situation remains volatile

SecuriFire FACP 3000	30 – 36 weeks
SecuriFire FACP 2000	29 – 38 weeks
SecuriFire FACP 1000	20 – 22 weeks
SecuriFire FACP 500	20 – 25 weeks

# SecuriFire modules/boards:

The production runs steady, but at limited capacity, due to insufficient component supply.

BX-OI3	28 – 38 weeks
BX-REL4	40 – 49 weeks
BX-IOM	36 – 42 weeks
BX-AIM	16 – 22 weeks
BX-O2I4	26 – 36 weeks
B8-BAF	26 – 35 weeks
B8-OM8	29 – 37 weeks
B8-DXI2	30 – 35 weeks
BX-O1	24 – 28 weeks

#### Addressable multi criteria detector

Production runs at full capacity on MCD 573X. Production of MCD 573X-SP runs at limited capacity, the situation remains volatile.

MCD 573X	27 – 29 weeks
MCD 573X-S	36 – 40 weeks

# Manual Call Point

Lead-times have been shortened and will further improve in the next weeks.

MCP 545X-1N	20 – 26 weeks
MCP 545X-4N	12 – 16 weeks

# Optical Smoke Switch

The production of the Smoke Switches has been increased, but lead-times remain long due to high market demand.

ORS 142 all models 28 – 32 weeks	1 ORS 142 all Illouels	28 – 32 weeks
----------------------------------	------------------------	---------------

Please always try to order your goods as early as possible and plan for enough lead-time.

Our sales administration team is constantly trying to prioritise orders and is in close contact with our customers. We are seeing improvements in many product lines and are optimistic that the situation will keep getting better week after week.

We sincerely apologise for all the inconvenience this situation is causing you, we thank you for your understanding and patience and we assure you that we do everything to improve the current situation as fast as possible. We will continue to keeping you informed once the situation changes.

Yours sincerely

Securiton AG

Adrian Liechti

Vice President Sales International

Marcus Schrimpl

Director Sales Administration